

Fig. 1






Fig. 2



COPY 11/1/00

Fig. 3



60760-111600

Fig. 4









Fig. 5



66773" in the 660

Fig. 6

300 LASER PRINTER 1660 Find device 307 305 http://133.151.92/printer/find.htmlt

Device Name		IP Address
	LJ SLEEP 001P MP Laser Printer HL-1660e	133.151.33.81
	(Printer Firmware Version: 1.04, Network Board Firmware Version: 3.42P (INTERIM))	
	LJ READY 001P T1 Laser Printer HL-1660e	133.151.120.70
	(Printer Firmware Version: 1.04, Network Board Firmware Version: 3.420 (INTERIM))	
	13 JAM REAR Color Laser Printer HL-2400C	133.151.33.67
	(Printer Firmware Version: 0.37, Network Board Firmware Version: 3.420 (INTERIM))	
	DON'T ACCESS ME ! Laser Printer HL-1600e	133.151.33.90
	(Printer Firmware Version: 1.04, Network Board Firmware Version: 3.42P (INTERIM))	

301 [Home Page] [View Configuration] [Control Panel] 303
 [Printer Settings] [On Line Support] [Administrator Settings] 310

Fig. 7




Fig. 8

400 405

Serial No.: 111646
 Ethernet Address 00-40-17-01-B4-1E

Firmware: V3.42 (INTERIM) 97.12.10
 Boot: V4.3

<http://133.151.120.92/nic/index.htm>

Configure Services	Configure Ports	Configure NetWare	Configure TCP/IP
Configure LAT	Configure AppleTalk	Configure NetBEUI	Configure Banyan
Configure DLC	Future	Future	Configure Password

Enabled Protocols: AppleTalk Banyan DLC LAT Network SNMP TPC/IP Win95/Peer

Print Test Page Reset Server Factory Defaults Reload Server

| Home | Help |

407